



Part #: OBEXMCNG-3VR3GD

Closure Instruction for Up to 3 Virtual Reality Goggles or 3 General Devices

Important Note

This closure instruction includes the assembly instructions for this packaging design. Substitution of materials or a change to these closure instructions may cause non-compliance with regulations and void the test certification for the packaging.

PRODUCT COMPONENTS

INCLUDED WITH THE PACKAGING
One (1) - Assembled Corrugated Box with
Interior Components (OPK—1-1.6-VR/GD/B-3)

Verify that there are no tears, punctures, split seams or rips in the exterior of the package or in any of the interior components. If you find any of these defects, DO NOT USE THE PACKAGING. Please contact the customer service department to order replacement special permit package(s).

INTERIOR COMPONENTS

QUANTITY PER PACKAGE	DESCRIPTION	STYLE NUMBER
1	Shipper	1-1.6-VR/GD/B-3
1	Heat Shield	4-1.6-ALL
1	Virtual Reality Goggle/ General Device Tray	3-1.6-VR/GD/B-3
1	Bottom Tray	2-1.6-ALL
2	Packing Tape — 4"	5-1.6-ALL
1	Lithium Battery Label*	LB435S / LB435C-3481S

^{*} Please use the correct label based on your emergency service provider and discard unused labels.

Note: LB435S <u>must</u> be personalized with your UN number and emergency contact information.

Emergency service providers require a contract prior to using their number.

ASSEMBLY INSTRUCTIONS



Inspect your package for defects.



Carefully open the top flap of the package.



Take the silver heat shield out of the package.



You should see a single sided tray for (3) virtual reality goggles or (3) general devices.

See other side for more instructions



If shipping virtual reality goggles, you must ensure the vizor is **facing up**. Remove straps and any earphones if present, and place them under the vizor when shipping.



If shipping general devices, place the general devices face down in the holding tray.

STEP 6



Place the heat shield on top of the device. Make sure the red dot on the heat shield is facing away from the device.

STEP 7



When the heat shield is in place, you should see the red dot.

STEP 8



Close box lid, inserting locking tabs into slots. Use two 4" strips of tape centered on each locking tab.

STEP 9



In the lower right corner, attach the red and white lithium battery label (label must be completed with UN number/telephone information per 173.185(c)(3)(ii), as referenced in Section 7(d)(3) of the Special Permit).

It is the shipper's responsibility to ensure that all the requirements of the Special Permit have been fulfilled prior to offering the package in transportation